

The City of Danville, Virginia

WATER AND WASTEWATER TREATMENT DEPARTMENT

WATER TREATMENT
279 PARK AVENUE
DANVILLE, VIRGINIA 24541
(804) 799-6473

137594

WASTEWATER TREATMENT
RIVERVIEW INDUSTRIAL PARK
229 STINSON DRIVE
DANVILLE, VIRGINIA 24540
(804) 799-5137

May 2, 1991

Andrew Palestine (3HW24)
Remedial Project Manager
Environmental Protection Agency
841 Chestnut Street
Philadelphia, Pennsylvania 19107

Re: EPA Superfund Program - Proposed Plan
First Piedmont Rock Quarry/Route 719 Site
Danville, VA
April 1991

Dear Mr. Palestine:

This is to comment on the "Proposed Superfund Program Plan" presented at the public meeting at Bethel Baptist Church, RFD 3 (Route 360), Danville, VA on April 16, 1991.

The preferred alternative for remediating the contamination at the referenced site proposes treatment of leachate at a POTW. Danville's POTW is the likely treatment facility for this leachate. However, for Danville's POTW to treat the leachate it will have to meet all facility pretreatment standards and not be classified as a hazardous material under RCRA. Danville's POTW is not a "hazardous waste" treatment facility, and would have to have certification (preferably by EPA), that the leachate to be treated at its POTW is not a RCRA classified "hazardous material". Since the "First Piedmont Rock Quarry Site" is a "Superfund Site", materials or liquid waste from it carry the implication of being hazardous.

-continued-

ARR302552A

Andrew Palestine

-2-

April 24, 1991

Danville's POTW does accept and treat wastewater trucked to it under special permits and arrangements for payment for treatment. These arrangements have to be made prior to disposal of trucked waste at the POTW.

Danville is receptive to the "Proposed Superfund Program Plan" and will cooperate with EPA and the other interest to achieve an acceptable solution for the First Piedmont Rock Quarry/Route 719 Site.

Sincerely,

Herbert M. Dawson

Herbert M. Dawson
Director of Water & Wastewater Treatment

/chw

c John R. Sweeney
City Manager
Gary G. Shaw

AR302553